## Approved For Release 2002/01/02 CTA-RDP78B04747A000900040014-4

25X1A

25X1A

TO:

11 July 1963

TAB requires new instrumentation (Flexowriters and telecordex) due to frequent breakdown and accuracy reduction of present installations. Telecordex in solid-state could be used for replacement of the present tube type. The change from the present system would be the possible substitution of the teletype for hard copy production and a separate punch tape capability for production of the 7 (seven) channel (6 bits + parity) field data code for use in the Univac 490. This should fulfill their requirements if the telecordex can be made to program a teletype output and the seven (7) channel tape punch for the Univac 490 at the same time.

## Notes:

- 1. Auto carriage return has to be added to teletype?
- 2. To cover entire requirements the following should be obtained
  - a. Three (3) units for the RIC/l's.
  - b. One unit for the
  - c. One unit for the Comparator in house
  - d. One unit for the Comparator being purchased
  - e. Thus far a total of six (6) units are required.
- 3. Since we at one time requested support from GSA for teletype maintenance, modifications and/or repair should pose no problem.

25X1A

## **Declass Review by NIMA / DoD**